

1, Overview of the barn (large building to the left of the trees) and the ranch headquarters from the access road from County Road 196. View south.



CO\_Chaffee\_IrvingBarn\_0001

2, Front (south wall) of the barn. View north.



CO\_Chaffee\_IrvingBarn\_0002



3, Front (south wall) and west wall of the barn. View northeast.



CO\_Chaffee\_IrvingBarn\_0003

4, West wall of the barn with later addition to left. View east



CO\_Chaffee\_IrvingBarn\_0004



5, West and north walls of the barn with later addition to left. View southeast.



CO\_Chaffee\_IrvingBarn\_0005

6, North wall of the barn with the later addition to the left. View south.



CO\_Chaffee\_IrvingBarn\_0006



7, North and east walls of the barn with the later one-story addition in the foreground. View southwest.



CO\_Chaffee\_IrvingBarn\_0007

8, Interior, first story, east area. View east.



CO\_Chaffee\_IrvingBarn\_0008



9, Interior, loft. View east.



CO\_Chaffee\_IrvingBarn\_0009

10, South and east walls of the one-story addition with the south and east walls of the one-and-half-story section beyond. View northwest.



CO\_Chaffee\_IrvingBarn\_0010



11, East wall of the one-story addition with east and north walls of the one-and-half-story section beyond. View southwest



CO\_Chaffee\_IrvingBarn\_0011